

Oil Field Environmental Incident Summary

Incident: 20150408115530 **Date/Time of Notice:** 04/08/2015 11:55

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: SC-MARI-153-98- 2223H-1

Field Name: TRUAX

Well File #: 23642

Date Incident: 4/7/2015

Time Incident: 13:30

Facility ID Number:

County: WILLIAMS

Twp: 153

Rng: 98

Sec: 22

Qtr:

Location Description:

Submitted By: Jason Henry

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Tank Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	50	Barrels				

Description of Other Released Contaminant:

Approximately 50 bbls of fresh water was released from a faulty valve on an above ground storage tank.

Inspected:

Written Report Received: 7/8/2016

Clean Up Concluded: 4/9/2015

Risk Evaluation:

The source of the release was secured upon discovery, and the released fluid consisted of only fresh water with a trace amount of bactericide chem.

Areal Extent:

N/A - the release remained on the location.

Potential Environmental Impacts:

The release occurred above ground and remained on the location. Additionally, the released fluid consisted of only fresh water with a trace amount of bactericide chemical (approximately 0.012 bbls of bactericide to 50 bbls of fresh water). A soil sample will be collected from the area where the fresh

Action Taken or Planned:

The released fluid consisted of only fresh water with a trace amount of bactericide chemical (approximately 0.012 bbls of bactericide to 50 bbls of fresh water). A soil sample will be collected from the area where the fresh water pooled in order to verify that no soil remediation work is required. The soil sample will be analyzed for the constituents listed on the MSDS for the bactericide.

Wastes Disposal Location: It is anticipated that there will be no waste streams generated as a result of this fresh water release.

Agencies Involved:**Updates**

Date: 4/8/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on location according to the report. NDIC retains oversight.